

# General Environmental Incident Summary

**Incident:** 4187      **Date/Time Notice:** 8/5/2016

**DEM Incident No:**

**Responsible Party:** Crestwood

**Date Incident:** 8/4/2016

**Time Incident:** 1400

**Duration:** 30 minutes

**County:** Dunn

**Twp:** 148

**Rng:** 93

**Sec:** 15

**Qtr:**

**Lat:** 47.63654

**Long:** -102.50470

**Method:** Interpolation from map

**Location Description:** Near the Enerplus Bullhead pad. NWSW Sec. 14 T148N R93W. On pipeline ROW.

**Submitted By:** Joshua Swann

**Affiliation:**

**Address:** 10702 Hwy 73

**City:** Keene

**State:** ND

**Zip:**

**Received By:**

**Contact Person:** Josh Swann  
10702 Hwy 73  
Keene, ND

**Distance Nearest Occupied Building:**

**Release Contained:** Yes

**Type of Incident:** Pipeline Leak

**Description of Released Contaminant:** Produced Water

**Volume Spilled:** 100.00 barrels

**Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Reported to NRC:** No

**Cause of Incident:**

Installing new line, contractor stuck existing produced water line.

**Risk Evaluation:**

No immediate risks.

**# of Fatalities:** 0

**# of Injuries:** 0

**Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

Impacts to soils.

**Action Taken or Planned:**

Pumped out about 100 bbls of free product. Excavated down and in all directions until clean soil was found.

**Wastes Disposal Location:**

**Agencies Involved:** Tat Environmental, MHA Energy

## ***Updates***

---

***Date:*** 8/5/2016      ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Souder, Taylor

***Updated Volume:***

***Notes:***

Duplicate spill report